

● **Historical Context:**

- Developed in the late 19th century to measure alternating currents (AC).
- Complemented earlier direct current (DC) galvanometers.
- Emerged due to the rise of AC power distribution, pioneered by Nikola Tesla and George Westinghouse.
- Adapted from early DC galvanometers (Johann Schweigger, 1820) with modifications (moving-iron or moving-coil mechanisms).
- Widely used in education and laboratories for AC circuit studies.
- Aided understanding of inductance, capacitance, and resonance.
- Staple in mid-20th-century teaching and experimentation.
- Usage declined with the advent of oscilloscopes and digital meters.
- Now primarily of historical significance.

● **Purpose:**

- Measures alternating current (AC).
- Detects current magnitude and direction.
- Features a symmetrical scale around zero for positive and negative deflections.

● **Construction:**

- Magnetic Field and Coil:
- Coil suspended in a strong magnetic field.
- AC current interaction with the field causes coil oscillation.
- Mirror and Scale:
- Optional mirror attached to the coil.
- Reflected light beam amplifies deflection for reading.
- Damping System:
- Controls oscillation for steady readings.
- Compensates for the alternating nature of the current.

● **Applications:**

- AC Circuit Measurement:
- Measures small AC currents and voltages in laboratories.
- Used for educational demonstrations and experiments.
- Bridge Circuits:
- Used in AC bridge circuits for measuring inductance, capacitance, and resistance.
- Phase and Resonance Studies:
- Used in studies of phase shifts and resonance in AC circuits.
- Especially in experiments with LC circuits.

● **Instructions on How to Use Equipment:**

- Set Up the Galvanometer:
 - Place on a stable surface.
 - Ensure the needle is at zero when no current is applied.
- Connect to the Circuit:
 - Connect in series with the circuit.
 - Ensure tight connections.
- Power the Circuit:
 - Turn on the power.
 - Needle deflects in both directions based on current direction.
- Take Measurements:
 - Note needle deflection (right/positive, left/negative).
 - Measure the alternating current.
- Safety:
 - Avoid overloading the galvanometer.
 - Turn off power before disconnecting.
- After Use:
 - Store safely.
 - Recalibrate if needed.

Line for Inerting link.

.....
.....



References:

1. <https://www.tipl.com/product/lab-instruments>
1. <https://www.toshniwal.net/home>

<https://www.uou.ac.in/lecturenotes/science/BSC-17/Galvanometer%20Ammeter%20by%20Dr.%20Gaurav%20Karnatak.pdf>

